ISLANDS


PRE-TREATMENT ROUTES


BOWMORE / SPRINGBANK – Islay

CRAIGHOUSE - Jura

Route code	Description	Priority
I 1	A846 & B8016 Bridgend - Port Ellen	2
12	Bridgend –	_

Pregrit route





	from action plan	-	1			
12 - BRIDGEND	A846 PORT A	SKAIG AND A8	847 PORTNAH	HAVEN		
<u>District</u>	<u>Depot</u>	Loading Po	<u>int</u>		Route code	Priority
Islay	Bowmore	Springbank	salt depot		12	2
<u>Manoeuvre</u>	<u>Spinner</u>		Description			
Leave depot	Off	to springban	k salt store			
TURN RIGHT	ON	TREAT A846	6 TO PORT A	SKAIG FER	RY TERMINAL	
RETURN	off	Dead run to	CAOL ILA jui	nction,		
TURN RIGHT	ON	CAOL ILA T	O BUS STOP	, turn in nex	t junction and re	eturn
RETURN	off	Dead run to A846 / A847 junction, Bridgend				
RIGHT TURN	ON	A847 BRIDG	SEND TO PO	RT CHARLO	TTE	
AHEAD	ON	PORT CHAF	PORT CHARLOTTE TO PORTNAHAVEN - END OF HIGH ST			
RETURN	off	Dead Run - High St to Crown St (Port Wemyss - Bus Route)				
TURN RIGHT	ON	PORT WEMYSS - CROWN ST , SHORE ST and MAIN ST to A847				
RETURN	off	Dead Run -	Return to Spr	ingbank unlo	ad	
Salt requireme	nts					
Minimum Tonna		10g / sq.m 20g / sq.m. 40g / sq.m.	4.176	tonnes tonnes tonnes		

